

Project: Alaska Copper Works			Inspection Date:		5/30/19	
Project No.: 19ACV	<b>N</b> 1				Technician:	David DuBois
System Performance	<u>:e:</u>					
Was system running o	during the inspection	on? ⊠ Yes	□ No			
Flow Rates (gpm)	Influen	t <u>n/a</u>	Effluent _	n/a	The flows sh	nould be ~155 gpm
Bag Filter #1 Pressure	s (psi) Influen	t <u>8</u>	Effluent _	8		ers should be replaced
Bag Filter #2 Pressure	s (psi) Influen	t 8	Effluent _	8	— ir amerenua	al pressure > 8 psi
Carbon Filter Pressure	es (Lead) Influen	t n/a	Effluent _	n/a	The carbon filters should be backflushed if differential pressure > 8 psi	
Carbon Filter Pressure	es (Lag) Influen	t n/a	Effluent _	n/a		
Were the bag filters re	eplaced? 🗵 Yes	□ No				
Was the carbon backf	flushed?   Yes	⊠ No				

## **Maintenance and Inspection Checklist:**

Task	Completed (Y/N)	Issues/Notes/Comments
Walchem Controller Inspected	⊠ Yes □ No	
Flow Meters Inspected	⊠ Yes □ No	
Level Sensor Cleaning/Inspection	⊠ Yes □ No	
Inspect System Plumbing	⊠ Yes □ No	Drip on pretreat decant line between tanks
Pumps Inspected	⊠ Yes □ No	
General Housekeeping	☑ Yes ☐ No	
Chemistry Level	☑ Yes ☐ No	~70 gal
Safety Materials Inspected	⊠ Yes □ No	
pH Probe Inspection/Calibration	⊠ Yes □ No	



Water Sampling:								
Were water samples taken? ☐ Yes ☒ No								
Raw water:	pH <u>n/a</u>	Turbidity n/a	NTU					
Bag Filter Influent	pH7.56	Turbidity 6.84	_NTU					
Bag Filter Effluent	pH 7.51	Turbidity 3.81	_NTU					
Carbon Filter Influent	t pHn/a	Turbidityn/a	_NTU					
Carbon Filter Effluent	t pH <u>n/a</u>	Turbidity n/a	NTU					
Monthly Tasks:								
Were samples submitted to Analytical? ☐ Yes ☒ No								
Analytical Lab:		-						
Was Walchem data downloaded? ☐ Yes ☒ No								
Were the tank sludge	e levels checked?	☐ Yes 図 No						
Sludge Depth (inches	<b>)</b> :							
Decant Tank:	n/a							
Treatment tank:	n/a							
Backflush tank:	n/a							
Main lift station:	n/a							
North lift station:	n/a							
South lift station:	n/a							
Additional Comment	s. Recommendatio	ons and System Upse	ts:					
No water in vault Replaced cartridg	and no water di	scharged to carbo						
David DuBo	ois	Project Lead Te	ch	5/30/19				

Submit

Title

Technician

Page 2 of 2

Date